



Electronic Indicator Operating Manual Analog Display

Analog Visual Display
Incremental Measuring Mode
SPC Cables USB, MTI, RS232
Measuring System in English or Metric
Travel Reverse
Auto off
Rotating Bezel
Internal and External Serial Numbers
T.I.R. with Low & High Storage Recall

Power with Batteries
Power by AC Jack or Data Output
Programmable Lock Combination
User Tolerance Settings (high & low)
Up to 4 User Changeable Resolutions
Inch/Metric Display Conversion
Maximum Reading Hold
Display/Freeze Reading Hold
Minimum Reading Hold
Absolute/Preset Measuring Mode

TABLE OF CONTENTS

| | |
|---|----|
| Power Source Options | 3 |
| Button Functions..... | 4 |
| Summary Chart For Analog Button Actions | 5 |
| Display-Operating Prompts & Conditions..... | 6 |
| Power On/Off | 7 |
| Auto-Off Toggle..... | 7 |
| Travel Reverse Toggle | 7 |
| Change Units..... | 8 |
| Hold Mode..... | 8 |
| Tolerance On/Off | 9 |
| Tolerance Settings | 9 |
| Set High Tolerance Number..... | 10 |
| Set Low Tolerance Number..... | 10 |
| Set Absolute Number..... | 11 |
| Lock Toggle..... | 12 |
| Lock Combination..... | 12 |
| Reset to Factory Defaults | 13 |
| Verify Data I/O Type | 13 |
| Set Gage Resolution | 14 |
| Display Setup Mode..... | 14 |
| TIR Mode..... | 15 |
| Custom Applications..... | 16 |

CHOICE OF THREE POWER SOURCES

1. Batteries

The lithium battery used in this indicator is an IEC standard, type CR2450. The indicators are shipped with the batteries installed.

Note: This indicator has an **AUTO-OFF** feature to conserve battery life. After 10 minutes of “no activity” (no key presses or spindle movement), the gage will turn itself off. This feature may be disabled if continuous operation is desired; see **AUTO-OFF** On/Off instructions in this book.

Installing Batteries

Using a narrow screwdriver, gently pry under the tab on the left side of plastic bezel and slide out the battery tray as you turn the indicator face side down.

Insert two batteries, “+” side up, into tray cavities, then slide the tray back into its bezel slot, taking care that the batteries stay in proper position.

2. AC Adapter


First insert the mini-plug into the socket on the lower right side of the bezel, then plug the adapter into a wall outlet.

3. Data I/O Connector

Power also may be provided through the data I/O connector, for special fixturing or applications where the indicator is integrated with another piece of equipment. A ripple-free 5 VDC regulated voltage source is required.

BUTTON FUNCTIONS

| Key | Function Controlled |
|-----------------|--|
| OFF/MODE | <i>Off</i> – turns indicator off <i>MODE</i> – controls absolute numbers & display setup |
| ON/CLR | <i>On</i> – turns indicator on <i>CLR</i> – resets the <i>Lock Toggle</i> , <i>Data I/O Type</i> , <i>gage resolution</i> , and <i>Display</i> setup mode |
| HOLD | Allows you to hold the value on the display according to the specified Mode (<i>MAX</i> , <i>MIN</i> , <i>FRZ</i>) |
| IN/MM | Controls the display units (default is English) |
| 2ND | Controls the <i>Lock Toggle</i> , <i>Data I/O Type</i> , <i>gage resolution</i> , <i>Travel Reverse</i> , <i>Auto Off</i> and <i>Display</i> setup mode |
| TOL | Controls <i>Low</i> , <i>High</i> and <i>On</i> tolerance settings |




SUMMARY CHART FOR ANALOG BUTTON ACTIONS

Button actions occur on the press of the button in most cases. Some button presses will have the action occur on the release of the button press. For example, when the 'ON/CLR' button is used to clear the display, the action is to happen on the release of the button. When the 'ON/CLR' button is used as the 2nd function in a sequence of button pushes, the action can be on the press of the button. Whenever a button press requires a continuous press to scroll through some selection process, the action of the button is on the release of the button.

| BUTTON | FUNCTION | | | |
|-----------------|---|---|---|---|
| | PRIMARY | SUBSIDIARY | 2ND FUNCTION | 3RD FUNCTION |
| HOLD | <ul style="list-style-type: none"> Toggle on/off | <ul style="list-style-type: none"> Select hold type (MAX, MIN, FRZ) press and hold to step through selection Apply function | | <ul style="list-style-type: none"> Enter resolution select process* (2ND, ON/CLR, HOLD) |
| IN/MM | <ul style="list-style-type: none"> Toggles between inches, millimeters | | <ul style="list-style-type: none"> Toggles travel reverse (normal/reverse) | <ul style="list-style-type: none"> Resets to factory default settings (2ND, ON/CLR, IN/MM) |
| 2ND | <ul style="list-style-type: none"> Enables 2ND functions | <ul style="list-style-type: none"> Move function | | <ul style="list-style-type: none"> Verify data out put (2ND, ON/CLR, 2ND) |
| TOL | <ul style="list-style-type: none"> Toggles tolerance on or off | <ul style="list-style-type: none"> Select high or low to view or set numbers* Change function | <ul style="list-style-type: none"> Enter preset setting process* | <ul style="list-style-type: none"> Toggles lock on and off; press and release (2ND, ON/CLR, TOL) Enters user lock combination setting mode (press and hold to access setting mode)* |
| ON/CLR | <ul style="list-style-type: none"> Turn gage on | <ul style="list-style-type: none"> Clears/resets display to '0' or spindle position, or 'abs' number or 'abs' +/- spindle position | <ul style="list-style-type: none"> Enables 3RD function | |
| OFF/MODE | <ul style="list-style-type: none"> Turns gage off | <ul style="list-style-type: none"> Select measurement mode (INCR, ABS, TIR) press and hold to step through selection | <ul style="list-style-type: none"> Toggles auto-off on and off | <ul style="list-style-type: none"> Enter display selection style* (2ND, ON/CLR, OFF/MODE) |

* Note: apply, move and change are automatically active when in preset, lock and tolerance setting modes. Apply and change are automatically active when in resolution set mode.

DISPLAY-OPERATING PROMPTS & CONDITIONS



OPERATING INSTRUCTIONS

Power On/Off

To turn the unit on, press **ON/CLR**. To turn off, press **OFF/MODE**.

Auto-Off Toggle

To turn the **Auto-Off** function on or off, press the **2ND** button (**2ND ICON** should appear on the display). Press the **OFF/MODE**.

An hour glass appears at the left side of the display if **AUTO OFF** is active. If **AUTO OFF** is active the indicator will power off in 10 minutes with no activity (button press or spindle movement).



Travel Reverse Toggle

To change count direction:

Press **2ND** button, then press the **IN/MM** button.

Note: When arrow is pointed down ▼, the display counts down with inward spindle movement for **INCR** and **ABS**.

When the arrow is pointed up ▲, display counts up with inward spindle movement. For most applications this is the normal setting.



OPERATING INSTRUCTIONS

Change Units

To change the display units, press the **IN/MM** button.

Default unit of measure is set at the factory for English or metric scales.



Hold Mode

Allows you to hold the value on the display according to the specified mode.


Press **HOLD** to toggle hold mode on and off.

MAX – Holds and displays the highest reading attained.

MIN – Holds and displays the lowest reading attained.

FRZ – Holds and displays the reading displayed when **HOLD** is engaged.

To select type of **HOLD** (**MAX**, **MIN**, **FRZ**):
Press **HOLD** until desired feature is flashing, then release **HOLD**.




Note: Pressing **ON/CLR** button resets indicator to spindle position except in FRZ; resets to zero

OPERATING INSTRUCTIONS

Tolerance On/Off

Press **TOL** to toggle tolerance mode on and off. If no tolerances are programmed into the gage, then **tol** is displayed to indicate an invalid tolerance setting and the **HIGH** and/or **LOW** icons flash on and off.

When the tolerance settings are incorrect (high, low, or both) the corresponding icon or icons will flash.




Tolerance Settings

Continuously press the **TOL** button to activate the tolerance menu (**LOW**, **HIGH**, **ON**) and view the low and high tolerance settings.

If no preset tolerance number is set into the gage then zero will be displayed.

When viewing low or high, that icon will flash.




OPERATING INSTRUCTIONS

Set High Tolerance Number

To change to high tolerance settings:

Press **2ND** button (**2ND** icon should appear on the display). Press the **TOL (CHANGE)** button. High icon will be flashing.


Use the secondary function buttons, **CHANGE** and **MOVE** to set your tolerance setting. After you have set your high tolerance setting, press **APPLY** to store numbers to memory.



Set Low Tolerance Number

To change to low tolerance settings: Press **2ND** button (**2ND** icon should appear on the display). Press the **TOL (CHANGE)** button. Low icon will be flashing.

Use the secondary function buttons, **CHANGE** and **MOVE** to set your tolerance setting. After you have set your low tolerance setting, press **APPLY** to store numbers to memory.



Note: once high and low tolerances are set, the numeric readings will flash when your readings are out of tolerance.


The **LOW** or **HIGH** icon will flash indicating if the reading is under or over the tolerance.

OPERATING INSTRUCTIONS

Set Absolute Number


Press and hold the **OFF/MODE** button. When the icon on LCD appears above the **ABS** lettering, release the **OFF/MODE** button. If no preset number is stored in indicator **ABS** will show on display.

To change to absolute number (preset number), press **2ND** button; **2ND** icon should appear on the display. Press the **TOL** (**CHANGE**) button.



Use the secondary function buttons, **CHANGE** and **MOVE**, to set your absolute number. Press **MOVE** until the +/- or digit to be set is blinking.

Press the **CHANGE** button to reverse the +/- sign or change the value of the blinking digit. Repeat until the desired number is entered. Press **APPLY** to store absolute number to memory.




OPERATING INSTRUCTIONS

Lock Toggle

When the **LOCK** is on, all of the setting modes are disabled, and all 2nd and 3rd functions are disabled except the lock/unlock sequence.

Press the **2ND** button (**2ND** icon should appear on the display). Press **ON/CLR**. Press **TOL**. A key symbol will appear on the display when features are locked.




Lock Combination

Press the **2ND** button (**2ND** icon should appear on the display), then press **ON/CLR**. Continuously press **TOL** until **000** appears on the display.

Use the **CHANGE** and **MOVE** button to set your lock combination. After you have set your 3 digit lock combination press **APPLY**. A key symbol will appear on the display and your 3 digit combination is stored in memory.

WARNING: To change functions after the indicator has been locked with a combination, the correct combination must be applied.



Please contact the factory if the Lock Combination is lost.


OPERATING INSTRUCTIONS

Reset to Factory Defaults

This will set all features and functions back to the factory default settings.

Press the **2ND** button (**2ND** icon should appear on the display), followed by **ON/CLR**, then press **IN/MM**.


Note: Factory defaults cannot be reset if the **LOCK** feature is on.



Verify Data I/O Type

To view the Data I/O Type Output, press the **2ND** button. The **2ND** icon will appear on the display. Press **ON/CLR**. Press **2ND**. Format information is displayed on the LCD. **USB**, **SER**, **MTI**, or **BIPASS** will appear on the LCD.

To exit: Repeat button sequence.



OPERATING INSTRUCTIONS

Set Gage Resolution

For the change resolution feature: Press **2ND**, press **ON/CLR**, then press **HOLD**.

After that, each press of the **CHANGE** Button (**TOL**) steps through the available resolution options: **.001"**, **.0005"**, **.0001"** or **.00005"** *

*Note: Only resolutions coarser than indicator resolution-as-purchased are available.



Analog graduations are set to match gage resolution. Press the **APPLY** button to store the resolution setting. Display returns to measuring mode at desired resolution, but does not change displayed value.

Display Setup Mode

To change the display configuration, press the **2ND** button, followed by the **ON/CLR** button. Then press the **OFF/MODE** button to enter the display configuration setting mode.

The whole display flashes.

Press **CHANGE** to cycle through the display options and choose **APPLY** to save the current display configuration. There are five display options. For example, the analog display can be turned off or the numbers can be turned off.



OPERATING INSTRUCTIONS

TIR Mode



Total Indicator Runout (**TIR**) mode ignores travel direction, instead measuring the difference between peak and valley (**MAX** and **MIN**) values.

To enter TIR Mode, continuously press the **OFF/MODE** button until the diamond icon appears above the TIR function.

In TIR mode, the Freeze (**FRZ**) is the only hold function available.

To view the Peak (**MAX**) Value or the Valley (**MIN**) Value, use the **HOLD** button. Press **HOLD** button down until the **MIN** or **MAX** is displayed.

The difference between the **MIN** and **MAX** Values equals the TIR Value.



CUSTOM APPLICATIONS

Custom LCDs and graphics can be provided for almost any application. We can help you design a gage for your exacting requirements.

Keypads and features can be customized to meet most needs. For example, a gage can be programmed for T.I.R. only, or a gage can be programmed so only selected features are available.

With our programmable software and flexible microchip, the possibilities are limited only by your imagination.

Custom hardware is available to fit your specifications. For example, a gage can be made without a return spring or a custom spring. Special length stems, threaded stems, backs, and contact points, are also available.



Digital Indicators are available in the following travels and resolutions:

| Range/Travel | Resolution (operator changeable) |
|---------------------|---|
| .250" | .0001"/.002mm; .00005"/.001mm |
| .600" | .0005"/.01mm; .0001"/.002mm; .00005"/.001mm |
| 1.0" | .0005"/.01mm; .0001"/.002mm; .00005"/.001mm |
| 2.0" | .001"/.02mm; .0005"/.01mm; .0001"/.002mm |
| 4.0" | .001"/.02mm; .0005"/.01mm; .0001"/.002mm |